

CONVERSION TABLE OF GRADES FOR COPPER & ITS ALLOYS

Sort	China	America		United Kingdom	West Germany		Japan
	GB	ASTM	CDA	BS	DIN	Digital System	JIS
Copper	T2	C11000	110	C102	ECu-58	2.0090	C1100
Oxygen-free Copper	TU1	C10200	102	C103	OF-Cu	2.0040	C1020
Phosphorized Copper	TP1	C12000	-	C106	SW-Cu	2.0076 2.0090	C1201
		C12100	-	-	SF-Cu		C1220
	TP2	C12200	122	-	-		-
Silver-containing copper	TAg0.08	C13000	130	C101	CuAg0.1	-	C1271
		C12900	-	-	-	-	PP
	TAg0.1	-	-	-	-	-	-
Brass	H96	C21000	210	CZ125	CuZn5	2.0220	C2100
	H90	C22000	220	CZ101	CuZn10		C2200
	H85	C23000	230	CZ102	CuZn15		C2300
		C23000	-	-	-	2.0240	-
						-	
	H80	C24000	240	CZ103	CuZn20	2.0250	C2400
	H70	C26000	260	CZ106	CuZn30		C2600
		C26100	-	CZ126	-		-
	H68A	-	-	-	-	-	-
						-	
	H68	C26200	-	-	CuZn33	2.0280	C2680
	H65	C26800	268	CZ107	CuZn36		C2700
		C27000	270	-	-		-
	H63	C27400	272	CZ108	CuZn37	2.0321	C2720
		C27200	-	-	-		-
						-	
	H62	C28000	280	-	CuZn40	2.0360	C2800
	H60	C28000	280	CZ109	CuZn40		C2801
Leaded Brass	HPb63-3	C34500	345	CZ119	CuZn36pb1.5	2.0331	C3560
		C34700	347	CZ124	CuZn36pb3	-	-
	HPb63-0.1	C34900	-	-	CuZn37pb0.5	2.0332	-
	HPb60-2	C36000	-	CZ120	-	-	C3713
			-	-	-	-	C3604
	HPb59-2	C35300	-	-	CuZn32pb2	-	C3771
	HPb59-1	C37800	-	CZ122	CuZn39pb3	2.0380	C3710
	HPb58-2.5	C38000	-	CZ121	-	2.0401	C3603